

35t Status and Noise Update

20160330 - 35t - B.Kirby


High Voltage Status - A. Hahn High Voltage

- We were at 90 kV (375 V/cm) at time of last meeting.
- Attempts to raise the Cathode HV to 120 kV (500 V/cm) = 133.3 kV @ PS on Thursday were unsuccessful
 - Two trips, first at ~130 kV, second at 108 kV
 - Second trip we actually heard—suspect it was external to tank, nearby the PS or the first filter
 - Knocked out one of the Video Cameras—but no other camera actually saw anything
 - Camera rack is nearby the first HV filter, so that may be correlated??
 - Decided to think about it.
 - Set back to 90 kV on the Cathode—that held ok
- On Friday decided to find where it would hold
 - Raised HV ~10 kV per step, and waited to see if it would hold.
 - By the end of day we were at 120 kV!







"Nano" Discharges(??) @ 120 kV




"High Noise" State










Reminder - High-Noise State in Data


~2ms after




"High Noise State" Update - N.Barros Noise vs HV

- There is circumstantial evidence that noise increased with HV drift.
 - At 60 kV : No noise transitions (according to Alex)
 - At 90 kV : Short lived high noise and would recover on its own
 - At 120 kV: Often in high noise and only recovered when power cycling ASICs
- FEMB 9,10,12-15 were not being used (channel A powered off)
- Power cycling FEMB-00 was enough to recover low noise
- When started running with only RCE00,04 and 08 high noise became state less common
 - One FEMB per APA (except APA3)
 - Still doesn't recover on its own.

35t Noise - FFT and ~100kHz Modes on APA0



Reminder - APA0 Signals at Nominal Wire Bias



- Room temperature wire-bias tests performed in cryostat Oct 2015
- See frequent negative pulse signals in readout with nominal wire bias and 100pA leakage setting on APA0

Noise Plans

- Requested running with a single FEMB with ASICs turned on
 - Determine frequency of high noise states, see if there's a significant difference between boards
- Try reducing supply voltage to ASIC regulators
- Dedicated noise tests at Fermilab next week
 - List of tests has been compiled